

Keberadaan Kantor Desa dan Kondisi Bangunan
di Kabupaten Lebak Tahun 2017

No.	Kecamatan	Jumlah Desa	Keberadaan		Kondisi Bangunan		
			1. Ada	0. Tdk Ada	Baik	Rusak Ringan	Rusak Berat
[1]	[2]	[3]	[4]	[5]	[6]	[7]	[8]
1	Banjarsari	20	5	15	3	1	1
2	Bayah	11	11	0	9	2	0
3	Bojongmanik	9	7	2	2	4	1
4	Cibadak	15	13	0	11	3	0
5	Cibeber	22	21	1	5	14	2
6	Cigemblong	9	9	0	0	8	1
7	Cihara	9	9	0	8	1	0
8	Cijaku	10	10			9	1
9	Cikulur	13	13		1	10	2
10	Cileles	12	11	1	9	1	1
11	Cilograng	10	9	1	6	2	1
12	Cimarga	17	8	9	3	5	
13	Cipanas	14	12	2	1	9	2
14	Cirinten	10	9	1	6	2	2
15	Curugbitung	10	7	3	1	4	2
16	Gunung Kencana	12	12		6	6	
17	Kalanganyar	7	7	0	1	4	2
18	Lebak Gedong	6	6	0	6	0	0
19	Leuwidamar	12	11	1	7	2	2
20	Maja	14	14		4	9	1
21	Malingping	14	14		11	3	1
22	Muncang	12	6	6	6		
23	Panggarangan	11	11	0	3	7	1
24	Rangkasbitung	11	11		7	3	1
25	Sajira	15	10	5	1	4	5
26	Sobang	10	10	0	2	6	1
27	Wanasalam	13	13	0	0	10	3
28	Warunggunung	12	12		5	6	1
J u m l a h		340					

Sumber : Dinas Pemberdayaan Masyarakat dan Desa Kab. Lebak